




EAC

JMC 3D.1A




12		L=400	1	x3
13		Ø10		x6
1				x10
2				x8
3		Ø15		x8
4		M8		x4
5		h=60		x2
6		h=60		x2
7				x6
8		Ø12		x6
9		Ø20		x6
10		128		x3
11		M4x22		x6
14		6,3x11,5		x12
15				x1
16				x2
17		L=500		x1
18				x3
19				x3
20		3,5x16		x46
21				x2
22				x2
23				x1
24				x12


V




VI





VII




VIII



IX


$$X$$


XI



13  x6